

QUICK INSTALLATION GUIDE Windows 7, Vista & XP

**Warning: Install the software FIRST before connecting the USB or Serial lead.
Do not connect the power supply to the programmer until after the USB
or Serial lead is connected**

1. Insert the Installation CD. The CD should start automatically. (If the installation does not start automatically “Open” the CD drive from “My Computer” and “double-click” file name [Setup.exe](#)). Follow the on-screen instructions. **

- 2A. *Serial connection:*
 - *Connect the Programmer to a serial port on your PC using the supplied cable. Power up the unit using the supplied 24volt PSU.*
 - *Go to Control Panel, (System, Hardware), Device Manager, Ports and note the “COM” number against the Communications Port entry.*

- 2B **USB Connection:**
 - Connect the Programmer to a USB port on your PC using the supplied cable.
 - Power up the unit using the supplied 24volt PSU.
 - The New Hardware Found and Working OK should appear.
 - Go to Control Panel, (System, Hardware), Device Manager, Ports and note the “COM” number against the USB Serial Port entry.

3. Start the Programmer Module by clicking on the relevant Desktop Icon. When the Main Menu appears select the **COM Port** number found in the previous section.
4. For the Plus Module exit the Program to save the configuration.
5. For the Classic Module select the Language required as well and Click on **Save Config** and **Exit**.

** Windows7(64bit) An error message may appear regarding the installation of the USB driver. Click on OK. Browse to C:\Program Files(x86)\Mektek and “double-click” file **CDM20802_Setup** to run it. Installation is then complete.

Note: The COM Port must be set separately for each Module to be used.

QUICK INSTALLATION GUIDE Windows 98 & Me

**Warning: Install the software FIRST before connecting the USB or Serial lead.
Do not connect the power supply to the programmer until after the USB
or Serial lead is connected**

1. Insert the Installation CD. The CD should start automatically. An error message will appear saying that the Windows version is not suitable. Exit the message. Click on Run and type in the drive for the CD.
 2. Browse to find & select the folder Windows_98_ME. In this folder you will find 3 further folders – Mektek Classic, Mektek Plus and USB Drivers. Open the Mektek Classic and Mektek Plus folders in turn and run the Setup.exe file in each. The USB Drivers will be installed
- 3A. Serial connection:
- Connect the Programmer to a serial port on your PC using the supplied cable. Power up the unit using the supplied 24volt PSU.
 - Go to Control Panel, System, Hardware, Device Manager, Ports and note the “COM” number against the Communications Port entry.
- 3B. USB connection:
- Connect the Programmer to a USB port on your PC using the supplied cable.
 - Power up the unit using the supplied 24volt PSU.
 - The New Hardware Wizard will load – follow the instructions to install the drivers “automatically” from the CD.
 - When the drivers have been installed “USB Serial Found and Working OK” should appear.
 - Go to Control Panel, System, Hardware, Device Manager, Ports and note the “COM” number against the USB Serial Port entry.
4. Start the Programmer Module by clicking on the relevant Desktop Icon. When the Main Menu appears select COM Port number found in the previous section.
 5. For the Plus Module exit the Program to store the configuration.
 6. For the Classic Module select the Language required as well and Click on Save Config and Exit. To modify settings select Change Configuration in the main menu which will appear when the Programmer software is restarted.

Note: The Com Port must be set separately for each Module to be used.